




RDT-18K -
TELESCOPING POLE, 18 FT

CF-200 - WISPY™
MULTIPURPOSE WIRELESS
INSPECTION CAMERA

GOOSENECK

ADAPTER

INSTRUCTIONS FOR MOUNTING JONARD TOOLS WISPY™ TO THE JONARD TOOLS TELESCOPING POLE



1. Select the 8-32 to 1/4-20 adapter that is provided with the WISPY™
2. Screw the 8-32 end of the adapter into the hole on the top of the platform located on the TELESCOPING POLE



3. Screw the flexible gooseneck rod onto the 8-32 to 1/4-20 adapter
4. Screw the WISPY™ onto the end of the gooseneck as shown above

